


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 10032247	Main Street: MOSS_RD	Cross Street: N/A	Location: W
ADA ID: BEC56930A829	Ramp Type: BlendTrans2	Initial Pass/Fail: Pass	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 10			

	Possible Solutions:						
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	Compliance	Description	Data	Compliance	Description	Data
		N/A	Ramp Length (in)	97.0	Yes	BlendTrans Slope (%)	1.6
		Yes	Ramp Width (in)	60.0	Yes	BlendTrans XSlope (%)	0.1
		N/A	Flare Type LT	None	N/A	Flare Type RT	None
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	No	DWS Provided?	No
		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	No
		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R305</p>		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	No
		N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	No			
		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.1
		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.3
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To E		X Walk 2 Direction	N/A
			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	4.8		X Walk 2 Slope (%)	N/A
			X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A
<p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p>		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	0.2		Clear Space?	Yes
			Road X Slope (%)	4.8	N/A	Clear Space to XWalk (in)	N/A
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
			Obstruction Type			Storm Grate/Utility Type	
					N/A		N/A
					Yes	Surface Condition? (G/P)	Good
					No	Curb Slope (%)	34.0
Total Cost:		\$	3200.00				

