

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10038783 Main Street: STEELE CREEK RD **Cross Street: N/A** Location: SW ADA ID: BFB0ECE85191 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 22.5

Codes/Mitigation Info/Possible Solution



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 STEELE CREEK RD None **ENTRANCE** StopSign

Possible Solutions: **Remove & Replace Curb Ramp With Two New Directional Ramps or** Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost: 3200.00

Field Measurements/Component Compliance							
	Compliance Description		Data	Compliance Description		Data	
	N/A	Ramp Length (in)	58.0	No	Ramp	Slope (%)	10.1
	No	Ramp Width (in)	47.0	No	Ramp	XSlope (%)	2.3
	N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	Yes
		X Walk 1 Direction	To SE		X Wal	lk 2 Direction	To N
	N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	lk 2 Width (in)	94.0
		X Walk 1 Slope (%)	1.3		X Wal	lk 2 Slope (%)	1.5
		X Walk 1 X Slope (%)	1.2		X Wal	lk 2 X Slope (%)	8.6
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	Yes
		Road Slope (%)	1.5	N/A	Clear	Space?	N/A
		Road X Slope (%)	11.2	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
		Obstruction Type			Storm	Grate/Utility Type	
			N/A				N/A
				Yes	Surfac	ce Condition? (G/P)	Good
	軍	AL AL A					





