cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 42483 Main Street: BLAKENEY_GREENS_BV			Cross	Cross Street: BULLOCK_GREENWAY_BV				Location:	SW
ADA ID: BFBB16E3B9C9 Ramp Type: PerpDiag			Initial	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	17.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
The star 20		Remove & Replace Curb Ran	With	N/A	Ramp Length (in)	67.0	Yes	Ramp Slope (%)	5.1
		Two New Directional Ramps or		No	Ramp Width (in)	35.0	Yes	Ramp XSlope (%)	1.6
11307		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Mark H	Sen Cas			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	the second second			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and the second		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A Star	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
PROW/ADA: Not Found, R304.5.1				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	BULLOCK GREENWAY BV	-			X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	4.3
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	1.1
Street 2 Name	BLAKENEY GREENS BV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	0.7	N/A	Clear Space?	N/A
					Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

