

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

6.8

0.2

N/A

Good

Intersection ID: 7736 Main Street: EAGLES_LANDING_DR Cross Street: NATUREWOOD_CT Location: N

ADA ID: C00049060F23 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Flare Type RT



Street 1 Name

NATUREWOOD CT

Stop Condition-Street 2

StopSign

Street 2 Name

N/A

Stop Condition-Street 1

N/A

Possible Solution	Fleid Measurements/C		
Possible Solutions:	Compliance Description		Data
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	67.0
	No	Ramp Width (in)	44.5
	N/A	Flare Type LT	N/A
	N/A	Flare Slope LT (%)	N/A
	N/A	Flare Traversable LT?	N/A
	N/A	Landing Length (in)	N/A
Surveyor Notes:	N/A	Landing Width (in)	N/A
N/A	N/A	Landing Slope (%)	N/A
	N/A	Landing X Slope (%)	N/A
	N/A	Landing Curb? (Y/N)	N/A
	N/A	Shared Landing?	N/A
PROW/ADA:	N/A	Gutter Ponding?	N/A
Not Found, R304.5.1	N/A	Gutter Lip Ht (in)	N/A
	N/A	Painted X Walk1?	No
		X Walk 1 Direction	To S
	N/A	X Walk 1 Width (in)	N/A
		X Walk 1 Slope (%)	0.4
		X Walk 1 X Slope (%)	0.4
	N/A	Ramp inside XWalk1?	N/A
		Road Slope (%)	N/A
		Road X Slope (%)	N/A
	N/A	Any Obstructions?	N/A

1850.00





Total Cost:



Obstruction Type