cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			_								
Intersection ID: 7072	Main Street: GRAHAM_MEADOW_DR			Cross	Cross Street: JORDI_WY				Location:	S	
ADA ID: C085EFA82215	Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance:				o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description				
State 1	3 . O.	Remove & Replace Entire F	Ramr).	N/A	Ramp Length (in)	25.0	No	Ramp Slope (%)	11.6	
			·····r		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.1	
1 1 1 1 1	N. A. S				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
A A AMA	A MA				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Y VA	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	×/	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	n 40 - 1				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	1. 1				N/A	Shared Landing?	N/A		ζ, γ		
ALL ALL ALL ALL	11 200	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.2.2, R304.	53		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	1100				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	Se a se					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	JORDI WY	-				X Walk 1 Slope (%)	3.7		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	
								•			

Yes Surface Condition? (G/P)

Good

