

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19818 Main Street: CHERRYCREST_LN Cross Street: SCOTTRIDGE_DR Location: NW

ADA ID: C0B9AE4928FB Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 26.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

SCOTTRIDGE DR StopSign CHERRYCREST LN None Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance						
	Compliance Description		Data	Comp	liance Description	Data
ı	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	12.3
,	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.6
ı	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
ı	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
ı	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ı	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
ı	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
ı	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
ı	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
ı	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
ı	N/A	Shared Landing?	N/A			
ı	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
ı	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
ı	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To S		X Walk 2 Direction	To E
ı	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	2.8
		X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	0.9
l	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	2.4	N/A	Clear Space?	N/A
		Road X Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good
	V 1/100					





