

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16392 Main Street: QUEENS_RD_WEST **Cross Street: WELLESLEY_AV** Location: Ramp Type: MedianPerp **Overall Compliance: No ADA ID: C0E38B4916DA** Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution



QUEENS RD WEST Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:			
Remove & Replace Entire Ramp.			
	١		
	1		
	ı		
	ı		
	ı		
Surveyor Notes:	ı		
N/A	1		
	ı		
	ı		
	ı		
PROW/ADA:	ı		
Not Found, R304.2.2, R304.5.3	1		
	ı		
	ı		

Total Cost:	\$	1650.00

Field Measurements/Component Compliance							
Comp	liance Description	Data		liance Description	Data		
N/A	Ramp Length (in)	63.0	No	Ramp Slope (%)	8.7		
Yes	Ramp Width (in)	72.0	No	Ramp XSlope (%)	2.5		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
ANIX	M A TE	•	•	. ,			





