

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

10.1

3.2

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good

Surface Condition? (G/P)

Intersection ID: 9733 Main Street: LARRY_DR Cross Street: TUCKASEEGEE_RD Location: W

ADA ID: C0EB6B1ACE67 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name WILSON MIDDLE SCHOOL RD
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

10/1 0331bic Goldtion					ricia measurements/component compnance				
10	Possible Solutions:			Compliance Description		Data	ata Compliance Description		
	Remove & Replace Entire I	Ram	p.	N/A	Ramp Length (in)	46.0	No	Ramp Slope (%)	
	•		-	No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	
Phi.				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	
1	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	
	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	
牌				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	
1				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	
1				N/A	Shared Landing?	N/A			
3	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	
	Not Found, R304.5.1, R304	4.2.2	ī	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	
E M	R304.5.3			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	
100					X Walk 1 Direction	То Е		X Walk 2 Direction	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	
)					X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	
ı					X Walk 1 X Slope (%)	4.3		X Walk 2 X Slope (%)	
				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	
					Road Slope (%)	N/A	N/A	Clear Space?	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	
	Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	





