

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Good

								/	
Intersection ID: 11197	Main Str	Cross Stree	t: W_BROO	KSHIRE_RA		Location:	NW		
ADA ID: C0FE15C2D284	Ramp Ty	Initial Pass/Fail: Fail Overall Compliance			nce: N	o Severity Score:	10		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
ALLOW THE PARTY CARDING		Possible Solutions:				Compliance Description Data			
CAR AND	A SWEET A TAN	Remove & Replace Entire Ramp		Ramp Lengt			Ramp Slope (%)	7.0	
A MALE SALA STRAN	No. Not		No	Ramp Width	. ,		Ramp XSlope (%)	2.5	
and the second s	States and the states of the s	1	N/A	Flare Type L			Flare Type RT	N/A	
manual the di			N/A	Flare Slope			Flare Slope RT (%)	N/A	
			N/A	Flare Traver			Flare Traversable RT?	N/A	
and the second s			N/A	Landing Len			DWS Provided?	N/A	
8		Surveyor Notes:	N/A	Landing Wid	• • • •		DWS Contrast?	N/A	
		N/A	N/A	Landing Slo			DWS Length (in)	N/A	
E.		0/4	N/A	Landing X S			DWS Full Width?	N/A	
			N/A	Landing Cur	,		DWS Offset (in)	N/A	
54 St			N/A	Shared Land					
		PROW/ADA:	N/A	Gutter Pond	-		Gutter Slope (%)	N/A	
and a part	and R	Not Found, R304.5.1	N/A	Gutter Lip H	8		Gutter X Slope (%)	N/A	
	Not Found, R304.5.1	N/A	Painted X W			Painted X Walk2?	N/A		
Street 1 Name N GRAHAM ST			174	X Walk 1 Dir			X Walk 2 Direction	N/A	
			N/A	X Walk 1 Wi			X Walk 2 Width (in)	N/A N/A	
			N/A				( )	N/A N/A	
Stop Condition-Street 2				X Walk 1 Slo	,		X Walk 2 Slope (%)	N/A N/A	
Stop Condition-Street 2 Street 2 Name	Signal N/A		<b>N</b> //A	X Walk 1 X S	,		X Walk 2 X Slope (%)		
			N/A	Ramp inside			Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A			Road Slope			Clear Space?	N/A	
				Road X Slop			Clear Space to XWalk (in)	N/A	
			N/A	Any Obstruc		N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00	Obstruction			Storm Grate/Utility Type		
					N/A			N/A	

Yes Surface Condition? (G/P)

