



Intersection ID: 10025598		Main Street: E_WOODLAWN_RD		Cross Street: N/A		Location:		SE									
ADA ID: C1107582C437		Ramp Type: Combination1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 85									
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance													
		Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data			
		Remove & Replace Entire Ramp.		N/A		Ramp Length LT (in)		80.0		N/A		Ramp Length RT (in)		66.0			
				No		Ramp Width LT (in)		28.0		No		Ramp Width RT (in)		28.0			
				Yes		Ramp Slope LT (%)		5.3		No		Ramp Slope RT (%)		13.7			
				No		Ramp XSlope LT (%)		3.5		No		Ramp XSlope RT (%)		4.2			
				N/A		Ramp Length (in)		32.0		Yes		Ramp Slope (%)		5.1			
				Yes		Ramp Width (in)		48.0		No		Ramp XSlope (%)		9.8			
				N/A		Flare Type LT		N/A		N/A		Flare Type RT		N/A			
				N/A		Flare Slope LT (%)		N/A		N/A		Flare Slope RT (%)		N/A			
				N/A		Flare Traversable LT?		N/A		N/A		Flare Traversable RT?		N/A			
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.5.3, R304.3.2</p>				N/A		Landing Length (in)		N/A		N/A		DWS Provided?		N/A			
				N/A		Landing Width (in)		N/A		N/A		DWS Contrast?		N/A			
				N/A		Landing Slope (%)		N/A		N/A		DWS Length (in)		N/A			
				N/A		Landing X Slope (%)		N/A		N/A		DWS Full Width?		N/A			
				N/A		Landing Curb? (Y/N)		N/A		N/A		DWS Offset (in)		N/A			
				N/A		Shared Landing?		N/A									
				N/A		Gutter Ponding?		N/A		N/A		Gutter Slope (%)		N/A			
				N/A		Gutter Lip Ht (in)		N/A		N/A		Gutter X Slope (%)		N/A			
				N/A		Painted X Walk1?		No		N/A		Painted X Walk2?		N/A			
						X Walk 1 Direction		To W				X Walk 2 Direction		N/A			
<p>Street 1 Name</p> <p>None</p> <p>Stop Condition-Street 1</p> <p>ENTRANCE</p> <p>Street 2 Name</p> <p>N/A</p> <p>Stop Condition-Street 2</p> <p>N/A</p> <p>Total Cost:</p> <p>\$ 1800.00</p>						X Walk 1 Width (in)		N/A				X Walk 2 Width (in)		N/A			
						X Walk 1 Slope (%)		4.2				X Walk 2 Slope (%)		N/A			
						X Walk 1 X Slope (%)		7.7				X Walk 2 X Slope (%)		N/A			
				N/A		Ramp inside XWalk1?		N/A		N/A		Ramp inside XWalk2?		N/A			
						Road Slope (%)		N/A				Clear Space?		N/A			
						Road X Slope (%)		N/A		N/A		Clear Space to XWalk (in)		N/A			
												N/A		Any Obstruction?		N/A	
														Obstruction Type		N/A	
												N/A		Storm Grate/Utility Hazard?		N/A	
												Storm Grate/Utility Type		N/A			
				Yes		Surface Condition? (G/P)		Good									
												Curb Slope (%)		19.4			