


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 10029830		Main Street: KREFELD_DR		Cross Street: N/A		Location:		NW			
ADA ID: C11F0C7ED37C		Ramp Type: Directional1		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 0			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
				Possible Solutions:		Compliance		Description		Data	
				Remove & Replace Entire Ramp. Remove & Replace Gutter.		N/A		Ramp Length (in)		0.0	
<p>Surveyor Notes:</p> <p>DEBRIS COVERING RAMP</p>						N/A		Ramp Width (in)		0.0	
						N/A		Ramp Slope (%)		0.0	
						N/A		Ramp XSlope (%)		0.0	
						N/A		Flare Type LT		N/A	
						N/A		Flare Slope LT (%)		N/A	
						N/A		Flare Traversable LT?		N/A	
				No		Landing Length (in)		0.0		N/A	
				No		Landing Width (in)		0.0		N/A	
				No		Landing Slope (%)		0.0		N/A	
				No		Landing X Slope (%)		0.0		N/A	
PROW/ADA:				N/A		Landing Curb? (Y/N)		N/A		N/A	
				N/A		Shared Landing?		N/A		N/A	
R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R302.7.2, R304.5.4				Yes		Gutter Ponding?		0.0		No	
				No		Gutter Lip Ht (in)		0.0		No	
				N/A		Painted X Walk1?		N/A		Road Slope (%)	
						X Walk 1 Direction		N/A		Road X Slope (%)	
						X Walk 1 Width (in)		0.0		Clear Space?	
						X Walk 1 Slope (%)		0.0		N/A	
						X Walk 1 X Slope (%)		0.0		Yes	
				N/A		Ramp inside XWalk1?		N/A		Storm Grate/Utility Type	
				Yes		Any Obstructions?		N/A		N/A	
						Obstruction Type		N/A		N/A	
								N/A		Surface Condition? (G/P)	
								N/A		N/A	
Total Cost:				\$		2350.00					

