

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

62.5

53.0

8.0

5.7

6.0

0.9

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: FREEDOM DR Intersection ID: 11794 Cross Street: THRIFT RD Location: NW Initial Pass/Fail: Fail **Overall Compliance: No** 12.5 ADA ID: C12FB8C24CB4 Ramp Type: Combination1 **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

No

Yes

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

58.0

57.0

5.3

4.3

82.0

48.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name StopSign THRIFT RD Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Remove & Replace Sidewalk. Yes Yes No N/A Yes Surveyor Notes: N/A **RT RP < 5%** N/A N/A N/A N/A PROW/ADA: N/A R304.5.3 N/A N/A N/A

Total Cost:



2200.00

	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
		X Walk 1 Direction	ТоЕ		X Walk 2 Direction	N/A
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A
)	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A		Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		2,000		N/A	Any Obstruction?	N/A
					Obstruction Type	
1	III					N/A
		11=1		N/A	Storm Grate/Utility Hazard?	N/A
		the state of the s			Storm Grate/Utility Type	1477
						N/A
	-			Yes	Surface Condition? (G/P)	Good
		Jan San San San San San San San San San S			Curb Slope (%)	0.7

