

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28643 Main Street: BRYNFIELD DR **Cross Street: PROVIDENCE RD WEST** Location: SE **Severity Score:** 22.5 ADA ID: C194E90B7407 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 PROVIDENCE RD WEST None **BRYNFIELD DR**

StopSign

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost: 3200.00 Compliance Description Data Compliance Description Data No N/A Ramp Length (in) 60.0 Ramp Slope (%) 8.5 No Ramp XSlope (%) No Ramp Width (in) 40.0 2.4 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A **DWS Provided?** N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To NW X Walk 2 Direction To SW N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) X Walk 2 Slope (%) 0.4 1.3 X Walk 1 X Slope (%) 0.5 X Walk 2 X Slope (%) 0.2 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 1.0 N/A Clear Space? N/A N/A Road X Slope (%) Clear Space to XWalk (in) N/A 0.2 N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A

Yes

Surface Condition? (G/P)

Good





