

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.4

3.4

N/A

N/A

Main Street: WHITEHALL_EXECUTIVE_CENTERS SDStreet: N/A Intersection ID: 10041626 Location: Ν

Overall Compliance: No ADA ID: C1A518CC8F47 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 1.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

Data

70.5

95.0

N/A

N/A



WHITEHALL EXECUTIVE CENTER DR Street 1 Name Stop Condition-Street 2 StopSign N/A Street 2 Name Stop Condition-Street 1 N/A

ossible Solution		Field Me	
Possible Solutions:	Comp	liance Description	
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	
·	Yes	Ramp Width (in)	
	N/A	Flare Type LT	
	N/A	Flare Slope LT (%)	
	N/A	Flare Traversable LT	
	N/A	Landing Length (in)	
Surveyor Notes:	N/A	Landing Width (in)	
N/A	N/A	Landing Slope (%)	
	N/A	Landing X Slope (%	
	N/A	Landing Curb? (Y/N	
	N/A	Shared Landing?	
PROW/ADA:	N/A	Gutter Ponding?	
Not Found, R304.5.3	N/A	Gutter Lip Ht (in)	
	N/A	Painted X Walk1?	
		X Walk 1 Direction	
	N/A	X Walk 1 Width (in)	
		X Walk 1 Slope (%)	
		X Walk 1 X Slope (%	
	N/A	Ramp inside XWalk	
		Road Slope (%)	

1		ii	
	>		
	-		





