


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 28975	Main Street: BANNINGTON_RD	Cross Street: NORTHBURY_LN	Location: NW
ADA ID: C1A661BECEE6	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 60	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
 <p>Street 1 Name NORTHBURY LN</p> <p>Stop Condition-Street 2 StopSign</p> <p>Street 2 Name BANNINGTON RD</p> <p>Stop Condition-Street 1 None</p>	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		Yes	Ramp Slope (%)	6.0
			No	Ramp XSlope (%)	7.1
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Slope (%)	N/A
			N/A	Gutter X Slope (%)	N/A
			No	Painted X Walk2?	No
			To S	X Walk 2 Direction	To E
			N/A	X Walk 2 Width (in)	N/A
			6.1	X Walk 2 Slope (%)	1.8
			2.0	X Walk 2 X Slope (%)	6.3
			N/A	Ramp inside XWalk2?	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.5.3</p> <p>Total Cost: \$ 3200.00</p>			N/A	Clear Space?	N/A
			3.0	Clear Space to XWalk (in)	N/A
			4.7	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
			N/A	Obstruction Type	N/A
			N/A	Surface Condition? (G/P)	Good

