

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 19908 Main Street: BROWN-GRIER\_RD Cross Street: GALLANT\_LN Location: NE Ramp Type: Directional1 **Overall Compliance: No Severity Score:** ADA ID: C1B2C8492A5F Initial Pass/Fail: Fail 12.5

**Codes/Mitigation Info/Possible Solution** 



**BROWN-GRIER RD** Street 1 Name Stop Condition-Street 1 Signal Street 2 Name N/A Stop Condition-Street 2 N/A

| Section 1    | Possible Solutions:           |
|--------------|-------------------------------|
|              | Remove & Replace Entire Ramp. |
| 300          |                               |
| 200          |                               |
|              |                               |
| THE STATE OF |                               |
|              | Surveyor Notes:               |
|              | N/A                           |
|              |                               |
|              |                               |
| Me W         | PROW/ADA:                     |
| 200          | R304.5.3                      |
|              |                               |
| Mala         |                               |
|              |                               |
|              |                               |
|              |                               |
|              |                               |





Total Cost:



1600.00

| Field Measurements/Component Compliance |                       |       |        |       |                         |      |  |  |
|---|-----------------------|-------|--------|-------|-------------------------|------|--|--|
| Compli                                  | ance Description      | Data  | Compli | ance  | Description             | Data |  |  |
| N/A                                     | Ramp Length (in)      | 95.0  | N/A    | Grade | e Break?                | N/A  |  |  |
| Yes                                     | Ramp Width (in)       | 72.0  | N/A    | Grade | e Break Slope (%)       | 0.0  |  |  |
| Yes                                     | Ramp Slope (%)        | 0.6   | N/A    | Grade | e Break XSlope (%)      | 0.0  |  |  |
| No                                      | Ramp XSlope (%)       | 5.3   |        |       |                         |      |  |  |
| N/A                                     | Flare Type LT         | N/A   | N/A    | Flare | Type RT                 | N/A  |  |  |
| N/A                                     | Flare Slope LT (%)    | N/A   | N/A    | Flare | Slope RT (%)            | 0.0  |  |  |
| N/A                                     | Flare Traversable LT? | N/A   | N/A    | Flare | Traversable RT?         | N/A  |  |  |
| N/A                                     | Landing Length (in)   | 0.0   | N/A    | DWS   | Provided?               | N/A  |  |  |
| N/A                                     | Landing Width (in)    | 0.0   | N/A    | DWS   | Contrast?               | N/A  |  |  |
| N/A                                     | Landing Slope (%)     | 0.0   | N/A    | DWS   | Length (in)             | N/A  |  |  |
| N/A                                     | Landing X Slope (%)   | 0.0   | N/A    | DWS   | Full Width?             | N/A  |  |  |
| N/A                                     | Landing Curb? (Y/N)   | N/A   | N/A    | DWS   | Offset LT (in)          | N/A  |  |  |
| N/A                                     | Shared Landing?       | N/A   | N/A    | DWS   | Offset RT (in)          | N/A  |  |  |
| N/A                                     | Gutter Ponding?       | 0.0   | N/A    | Gutte | r Slope (%)             | N/A  |  |  |
| N/A                                     | Gutter Lip Ht (in)    | 0.0   | N/A    | Gutte | r X Slope (%)           | N/A  |  |  |
| N/A                                     | Painted X Walk1?      | Yes   |        | Road  | Slope (%)               | 4.8  |  |  |
|   | X Walk 1 Direction    | To S  |        | Road  | X Slope (%)             | 3.2  |  |  |
|   | X Walk 1 Width (in)   | 109.0 |        | Clear | Space?                  | N/A  |  |  |
|   | X Walk 1 Slope (%)    | 4.8   | N/A    | Clear | Space to XWalk (in)     | N/A  |  |  |
|   | X Walk 1 X Slope (%)  | 3.2   | N/A    | Storm | n Grate/Utility Hazard? | N/A  |  |  |
| N/A                                     | Ramp inside XWalk1?   | Yes   |        | Storm | n Grate/Utility Type    |      |  |  |
| N/A                                     | Any Obstructions?     | N/A   |        |       |                         | N/A  |  |  |
|   | Obstruction Type      |       | Yes    | Surfa | ce Condition? (G/P)     | Good |  |  |
|   |                       | N/A   | N/A    | Curb  | Slope (%)               | 3.8  |  |  |