


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: N/A	Main Street: AKRAM_CT	Cross Street: MARY_JO_HELMS_DR	Location: SE
ADA ID: C1B35B454D14	Ramp Type: Combination1Diag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 0	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
			N/A	Ramp Length LT (in)	38.5
			No	Ramp Width LT (in)	47.0
			Yes	Ramp Slope LT (%)	7.1
			No	Ramp XSlope LT (%)	2.3
			N/A	Ramp Length (in)	48.0
			No	Ramp Width (in)	41.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To N
				X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	1.4
				X Walk 1 X Slope (%)	2.1
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	7.1
				Road X Slope (%)	3.0
			N/A	Ramp inside XWalk2?	N/A
				Clear Space?	N/A
				Clear Space to XWalk (in)	N/A
				Any Obstruction?	N/A
				Obstruction Type	N/A
					N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	N/A
					N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	8.5

Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R304.5.1, R304.5.1, R304.5.3**

Total Cost:

**\$ 3200.00**

**N/A**

Street 1 Name **None**  
 Stop Condition-Street 1 **MARY JO HELMS DR**  
 Street 2 Name **StopSign**  
 Stop Condition-Street 2 **AKRAM CT**

