

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12265 Main Street: S_CHURCH_ST Cross Street: W_4TH_ST Location: N

ADA ID: C2295D0875CB Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 26.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

W 4TH ST Signal S CHURCH ST Signal Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes: **N/A**

PROW/ADA:

Not Found, R304.2.2, R304.5.3

4TH ST Signal RCH ST Signal

Total Cost: \$ 3200.00

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	52.0	No	Ram	Slope (%)	13.2
Yes	Ramp Width (in)	48.0	No	Ram	XSlope (%)	3.9
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	Yes
	X Walk 1 Direction	To SW		X Wa	lk 2 Direction	To SE
N/A	X Walk 1 Width (in)	105.0	N/A	X Wa	lk 2 Width (in)	115.0
	X Walk 1 Slope (%)	1.2		X Wa	lk 2 Slope (%)	2.0
	X Walk 1 X Slope (%)	1.8		X Wa	lk 2 X Slope (%)	2.5
N/A	Ramp inside XWalk1?	Yes	N/A	Ram	o inside XWalk2?	Yes
	Road Slope (%)	0.3	N/A	Clear	Space?	N/A
	Road X Slope (%)	2.9	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A

Surface Condition? (G/P)

Good





