

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5972 Main Street: DAWYCK_LN **Cross Street: SUNSTONE_DR** Location: NE Ramp Type: Directional1 **Overall Compliance: No** ADA ID: C230A9C76B07 Initial Pass/Fail: Fail **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution



DAWYCK LN Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions:					
Remove & Replace Entire Ramp.					
Surveyor Notes:					
N/A					
IN/A					
PROW/ADA:					
R304.5.1					

Total Cost: 1600.00

Field Measurements/Component Compliance						
Compli	ance Description	Data	Comp	iance Description	Data	
N/A	Ramp Length (in)	45.0	N/A	Grade Break?	N/A	
No	Ramp Width (in)	44.5	N/A	Grade Break Slope (%)	0.0	
Yes	Ramp Slope (%)	6.1	N/A	Grade Break XSlope (%)	0.0	
Yes	Ramp XSlope (%)	1.2				
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No		Road Slope (%)	3.2	
	X Walk 1 Direction	To W		Road X Slope (%)	3.9	
	X Walk 1 Width (in)	N/A		Clear Space?	N/A	
	X Walk 1 Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A	
	X Walk 1 X Slope (%)	3.9	N/A	Storm Grate/Utility Hazard?	N/A	
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
N/A	Any Obstructions?	N/A			N/A	
	Obstruction Type		Yes	Surface Condition? (G/P)	Good	
		N/A	N/A	Curb Slope (%)	N/A	





