

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 23940	Main Street: REA_RD	Cross Street: SWANS_RUN_RD	Location: SE
ADA ID: C24BDA409DCD	Ramp Type: ParaDiag	Initial Pass/Fail: Pass	Overall Compliance: Yes
Severity Score: 0			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

N/A

Surveyor Notes:

LT RP < 5%

PROW/ADA:

N/A

Street 1 Name REA RD  
 Stop Condition-Street 1 None  
 Street 2 Name SWANS RUN RD  
 Stop Condition-Street 2 StopSign

Total Cost: \$ 0.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	86.0	N/A	Ramp Length RT (in)	67.0
Yes	Ramp Width LT (in)	69.5	Yes	Ramp Width RT (in)	73.0
Yes	Ramp Slope LT (%)	4.4	Yes	Ramp Slope RT (%)	5.3
Yes	Ramp XSlope LT (%)	0.1	Yes	Ramp XSlope RT (%)	1.3
Yes	Landing Length (in)	71.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	72.5	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.9	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.0	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	Yes	Yes	DWS Offset (in)	2.0
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.4
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.7
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	0.7
	X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	0.5
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	0.4	N/A	Clear Space?	Yes
	Road X Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			Compliant	Curb Slope (%)	0.3

