

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Good

Surface Condition? (G/P)

Intersection ID: 13731 Main Street: CLEMENT AV Cross Street: E 9TH ST Location: Ε

Overall Compliance: No ADA ID: C273E2B20B02 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution

Possible Solutions:

Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1

Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 **CLEMENT AV** None E 9TH ST StopSign Total Cost:

3200.00

Comp	oliance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	28.0	Yes	Ramp	Slope (%)	5.5
No	Ramp Width (in)	47.5	Yes	Ramp	XSlope (%)	1.5
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
	X Walk 1 Direction	To NW		X Wa	lk 2 Direction	To SW
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.3		X Wa	lk 2 Slope (%)	2.7
	X Walk 1 X Slope (%)	0.3		X Wa	lk 2 X Slope (%)	1.4
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	1.9	N/A	Clear	Space?	N/A
	Road X Slope (%)	1.9	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storm	Grate/Utility Type	

Field Measurements/Component Compliance





