

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                           |                                    |                         |                        |
|---------------------------|------------------------------------|-------------------------|------------------------|
| Intersection ID: 10034403 | Main Street: PIEDMONT_ROW_DR_SOUTH | Cross Street: N/A       | Location: NW           |
| ADA ID: C274CB8556FF      | Ramp Type: BlendTrans2             | Initial Pass/Fail: Pass | Overall Compliance: No |
|                           |                                    | Severity Score: 2.5     |                        |

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R305.1.4, R305.2**

| Compliance | Description           | Data  | Compliance | Description                 | Data |
|------------|-----------------------|-------|------------|-----------------------------|------|
| N/A        | Ramp Length (in)      | 89.0  | Yes        | BlendTrans Slope (%)        | 2.3  |
| Yes        | Ramp Width (in)       | 60.0  | Yes        | BlendTrans XSlope (%)       | 1.8  |
| N/A        | Flare Type LT         | None  | N/A        | Flare Type RT               | None |
| N/A        | Flare Slope LT (%)    | N/A   | N/A        | Flare Slope RT (%)          | N/A  |
| N/A        | Flare Traversable LT? | N/A   | N/A        | Flare Traversable RT?       | N/A  |
| N/A        | Landing Length (in)   | N/A   | Yes        | DWS Provided?               | Yes  |
| N/A        | Landing Width (in)    | N/A   | Yes        | DWS Contrast?               | Yes  |
| N/A        | Landing Slope (%)     | N/A   | Yes        | DWS Length (in)             | 24.0 |
| N/A        | Landing X Slope (%)   | N/A   | No         | DWS Full Width?             | No   |
| N/A        | Landing Curb? (Y/N)   | No    | No         | DWS Offset (in)             | 4.0  |
| N/A        | Shared Landing?       | No    |            |                             |      |
| Yes        | Gutter Ponding?       | No    | Yes        | Gutter Slope (%)            | 1.9  |
| Yes        | Gutter Lip Ht (in)    | 0.0   | Yes        | Gutter X Slope (%)          | 1.5  |
| N/A        | Painted X Walk1?      | No    | N/A        | Painted X Walk2?            | N/A  |
|            | X Walk 1 Direction    | To SE |            | X Walk 2 Direction          | N/A  |
|            | X Walk 1 Width (in)   | N/A   |            | X Walk 2 Width (in)         | N/A  |
|            | X Walk 1 Slope (%)    | 2.3   |            | X Walk 2 Slope (%)          | N/A  |
|            | X Walk 1 X Slope (%)  | 0.5   |            | X Walk 2 X Slope (%)        | N/A  |
| N/A        | Ramp inside XWalk1?   | N/A   | N/A        | Ramp inside XWalk2?         | N/A  |
|            | Road Slope (%)        | 0.5   |            | Clear Space?                | Yes  |
|            | Road X Slope (%)      | 2.3   | N/A        | Clear Space to XWalk (in)   | N/A  |
| Yes        | Any Obstructions?     | No    | Yes        | Storm Grate/Utility Hazard? | No   |
|            | Obstruction Type      |       |            | Storm Grate/Utility Type    |      |
|            |                       |       | N/A        |                             | N/A  |
|            |                       |       | Yes        | Surface Condition? (G/P)    | Good |
|            |                       |       | No         | Curb Slope (%)              | 5.1  |

Total Cost: \$ 3200.00

|                         |          |
|-------------------------|----------|
| Street 1 Name           | ENTRANCE |
| Stop Condition-Street 1 | None     |
| Street 2 Name           | N/A      |
| Stop Condition-Street 2 | N/A      |

