


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 13046	Main Street: CENTRAL_AV	Cross Street: LAMAR_AV	Location: SE
ADA ID: C2928F86D23D	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance							
	Possible Solutions:			Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	70.5	No	Ramp Slope (%)	9.5		
		Yes	Ramp Width (in)	49.0	No	Ramp XSlope (%)	3.8		
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
Surveyor Notes:	N/A	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
		N/A	Shared Landing?	N/A					
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
			X Walk 1 Direction	To W		X Walk 2 Direction	N/A		
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
			X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	N/A		
			X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	N/A		
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
PROW/ADA:			Road Slope (%)	N/A	N/A	Clear Space?	N/A		
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
			Obstruction Type			Storm Grate/Utility Type			
					N/A		N/A		
					Yes	Surface Condition? (G/P)	Good		

Street 1 Name	LAMAR AV
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Total Cost:	\$	1850.00
-------------	----	---------

Total Cost: \$ 1850.00

