


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10014838	Main Street: THE_PLAZA	Cross Street: N/A	Location: NE
ADA ID: C29C63D2DD6C	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 10.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	107.0	Yes
			Yes	Ramp Width (in)	48.0	No
			N/A	Flare Type LT	Sloped	N/A
			N/A	Flare Slope LT (%)	9.3	N/A
			N/A	Flare Traversable LT?	No	N/A
			No	Landing Length (in)	N/A	Yes
			No	Landing Width (in)	N/A	Yes
			No	Landing Slope (%)	N/A	Yes
			No	Landing X Slope (%)	N/A	Yes
			N/A	Landing Curb? (Y/N)	No	Yes
			N/A	Shared Landing?	No	
			Yes	Gutter Ponding?	No	Yes
			Yes	Gutter Lip Ht (in)	0.0	Yes
			N/A	Painted X Walk1?	No	N/A
				X Walk 1 Direction	To W	
			N/A	X Walk 1 Width (in)	N/A	N/A
				X Walk 1 Slope (%)	1.4	
				X Walk 1 X Slope (%)	3.3	
			N/A	Ramp inside XWalk1?	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para</p>						
				Road Slope (%)	0.7	N/A
				Road X Slope (%)	3.0	N/A
			Yes	Any Obstructions?	No	Yes
				Obstruction Type		
						N/A
						Yes
						Good

Street 1 Name	ENTRANCE
Stop Condition-Street 2	StopSign
Street 2 Name	THE PLAZA
Stop Condition-Street 1	None

Total Cost: \$ 3200.00

