


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 4263	Main Street: DAVIS_LAKE_PY	Cross Street: SNOWS_ENTRY_PL	Location: N
ADA ID: C2A9A344786D	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 46.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		Compliance			Description			Data	
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	64.0	N/A	Grade Break?	N/A		
			No	Ramp Width (in)	43.0	N/A	Grade Break Slope (%)	0.0		
			No	Ramp Slope (%)	13.7	N/A	Grade Break XSlope (%)	0.0		
			No	Ramp XSlope (%)	6.1					
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0		
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A		
			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
Surveyor Notes:  N/A	PROW/ADA:		N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
	R304.5.1, R304.2.2, R304.5.3		N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A		
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A		
			N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A		
			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
			N/A	Painted X Walk1?	No		Road Slope (%)	8.3		
				X Walk 1 Direction	To SE		Road X Slope (%)	0.3		
				X Walk 1 Width (in)	N/A		Clear Space?	N/A		
				X Walk 1 Slope (%)	8.3	N/A	Clear Space to XWalk (in)	N/A		
Street 1 Name SNOWS ENTRY PL Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A				X Walk 1 X Slope (%)	0.3	N/A	Storm Grate/Utility Hazard?	N/A		
			N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type			
			N/A	Any Obstructions?	N/A			N/A		
				Obstruction Type		Yes	Surface Condition? (G/P)	Good		
					N/A	N/A	Curb Slope (%)	N/A		
	Total Cost:		\$	1600.00						

