

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 20158Main Street: GAULEY\_CRCross Street: GRIERS\_FORK\_DRLocation:NEADA ID: C2B96CC0E29DRamp Type: PerpDiagInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:10

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

GRIERS FORK DR None GAULEY CR StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Compliance Description		Data	Comp	liance Desc	ription	Data
N/A	Ramp Length (in)	47.0	Yes Ramp Slope (%)		7.3	
No	Ramp Width (in)	36.0	No	Ramp XSlope (%)		3.0
N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope	RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Trave	rsable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provi	ded?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contr	ast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Lengt	th (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full V	Vidth?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offse	t (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slop	e (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X SI	ope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X V	Valk2?	No
	X Walk 1 Direction	To NW		X Walk 2 D	irection	To SW
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 W	idth (in)	N/A
	X Walk 1 Slope (%)	1.4		X Walk 2 S	lope (%)	1.7
	X Walk 1 X Slope (%)	0.0		X Walk 2 X	Slope (%)	2.3
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp insid	e XWalk2?	N/A
	Road Slope (%)	0.5	N/A	Clear Spac	e?	N/A
	Road X Slope (%)	1.8	N/A	Clear Spac	e to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grat	e/Utility Hazard?	N/A
	Obstruction Type			Storm Grat	e/Utility Type	
		N/A				N/A
			Yes	Surface Co	ndition? (G/P)	Good





