

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7376	Main Street: RIBBLE_CT			Cross	Cross Street: SILCHESTER_LN				Location: E		
ADA ID: C300638C946F	Ramp Ty	amp Type: Combination1			Initial Pass/Fail: Fail Overall Complian			nce: N	o Severity Score:	55	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	AND LEVE	Possible Solutions:			Compliance Description		Data Compliance Description			Data	
	1	Remove & Replace Ent	ire Ram	מו.	N/A	Ramp Length LT (in)	59.5		Ramp Length RT (in)	29.0	
1.00				.6.	No	Ramp Width LT (in)	33.5	No	Ramp Width RT (in)	47.0	
	S.				No	Ramp Slope LT (%)	11.9	Yes	Ramp Slope RT (%)	6.5	
					No	Ramp XSlope LT (%)	10.0	No	Ramp XSlope RT (%)	9.3	
San San					N/A	Ramp Length (in)	27.0	Yes	Ramp Slope (%)	7.5	
					Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	10.0	
	- 2 -	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
K E		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	and the second				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	and a				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	and the second				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	1 1	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	C. The	Not Found, R304.5.1, R	304.5.3		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
Contact (Bar and a second	R304.3.2		, ,	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
A A A A A	Read a				N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	RIBBLE CT				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	7.0		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	6.7		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
						200		N/A	Any Obstruction?	N/A	
									Obstruction Type	N/A	
	State of the second sec	A stand of the second stand of the			-			1		177	

- N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A
- Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 22.8





