

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17555Main Street: E_WOODLAWN_RDCross Street: OLD_PINEVILLE_RDLocation:NEADA ID: C32B04F29CD1Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
OLD PINEVILLE RD
Stop Condition-Street 2
Signal
Street 2 Name
N/A
Stop Condition-Street 1
N/A

1	Possible Solution	Field Measurements/Component Compliance					
	Possible Solutions:	Comp	liance Description	Data	Comp	liance Description	Data
	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	99.0	No	Ramp Slope (%)	8.6
		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.0
200		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Š		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
1		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
1	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
,		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
900		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
8		N/A	Shared Landing?	N/A			
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
ì	•	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
è			X Walk 1 Direction	To W		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	N/A
			X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 1850.00		Obstruction Type		l	Storm Grate/Utility Type	
				N/A			N/A
					Yes	Surface Condition? (G/P)	Good





