

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

61.0

48.0

0.9

2.6

5.3

2.2

N/A

No

To N

N/A

1.3

1.6

N/A

N/A

Intersection ID: 32013 Main Street: RIDGE CREEK DR **Cross Street: GENERAL DR** Location: SW **Overall Compliance: No Severity Score:** ADA ID: C331675DF576 Ramp Type: Combination1Diag Initial Pass/Fail: Fail 0

**Codes/Mitigation Info/Possible Solution** 

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

None **GENERAL DR** StopSign RIDGE CREEK DR

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: RT RP < 5% PROW/ADA: Not Found, R304.5.1, R304.5.3

Total Cost:

Compliance Description Data Compliance Description N/A N/A Ramp Length LT (in) 51.0 Ramp Length RT (in) No Ramp Width LT (in) 46.0 Yes Ramp Width RT (in) Yes Ramp Slope LT (%) 5.2 Yes Ramp Slope RT (%) Ramp XSlope LT (%) 2.8 No Ramp XSlope RT (%) No N/A Ramp Length (in) 48.0 Yes Ramp Slope (%) Ramp Width (in) 51.0 No Ramp XSlope (%) Yes N/A Flare Type LT N/A N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A **DWS Contrast?** N/A Landing Width (in) N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? To E X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) X Walk 2 Slope (%)

3.6

1.2

N/A

2.2

N/A

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)







N/A

3200.00

N/A Any Obstruction? N/A Obstruction Type
Obstruction Type
oboli dollori Typo
N/A
N/A Storm Grate/Utility Hazard?
Storm Grate/Utility Type
N/A
Yes Surface Condition? (G/P) Good
Curb Slope (%) 11.3

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?