

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Surface Condition? (G/P)

Curb Slope (%)

Good

16.1

Yes

Intersection ID: 53962	ction ID: 53962 Main Street: LILAC_TREE_AV					DENBUR_DR	Location: N				
ADA ID: C362D12D6D26	Ramp Type: Combination1				Initial Pass/Fail: Fail Overall Complian				ice: No Severity Score: 22.5		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
Possible Solutions:					Compliance Description		Data Compliance Description			Data	
	FL W W	Remove & Replace En	tire Ramp		N/A	Ramp Length LT (in)	71.0	N/A	Ramp Length RT (in)	72.0	
					Yes	Ramp Width LT (in)	59.5	Yes	Ramp Width RT (in)	60.0	
					No	Ramp Slope LT (%)	9.0	Yes	Ramp Slope RT (%)	6.4	
I III I I IIII I IIII	in a				Yes	Ramp XSlope LT (%)	0.6	No	Ramp XSlope RT (%)	2.9	
					N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	3.9	
					No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	1.6	
1 1 1 2 and 1		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
- Barris Contraction of the second se	16 - 14 mil	N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
<u>k</u>	All and a second second				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	No.				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
E BEAN & G	- des	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
R. C. Mile	100-	Not Found, R304.5.1,	R304.3.2,		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
B B	1 mar	R304.5.3	,		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
0.00	1 Martin				N/A	Shared Landing?	N/A				
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1 D	ENBUR DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$1	800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
						in the		N/A	Any Obstruction?	N/A	
									Obstruction Type		
										N/A	
		the second and the second second						N/A	Storm Grate/Utility Hazard?	N/A	
									Storm Grate/Utility Type		
						-				N/A	



