

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

44.0

60.0

12.7

3.8

5.7

7.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 16587 Main Street: NORTH\_FALLS\_DR Cross Street: W\_TYVOLA\_RD Location: SW

ADA ID: C3828E7C4EEB Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 58.75

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

Yes

Yes

Yes

N/A

No

N/A

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

N/A

Yes

No

No

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Flare Traversable RT?

Data

73.0

60.0

8.0

0.6

60.5

46.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A



Street 1 Name

YieldSign
Stop Condition-Street 1

Street 2 Name

N/A
Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

LT RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.5.3, R304.3.2

Total Cost:



1800.00

	•			,	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	110.0		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	5.2		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
En l			N/A	Any Obstruction?	N/A
	The state of the s			Obstruction Type	
					N/A
	May to		N/A	Storm Grate/Utility Hazard?	N/A
	1-1-			Storm Grate/Utility Type	IV/A
7					N/A
			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	15.8