


Intersection ID: 52449		Main Street: TRANQUIL_OAK_PL		Cross Street: PAT_GARRETT_ST		Location:		SE							
ADA ID: C3976E673E15		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 13.75							
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance											
<div><div>Possible Solutions: Remove & Replace Entire Ramp.</div><div>Surveyor Notes: N/A</div><div>PROW/ADA: R304.2.2, R304.5.3</div></div> <td colspan="2">Compliance</td> <td colspan="2">Description</td> <td colspan="2">Data</td> <td colspan="2">Compliance</td> <td colspan="2">Description</td> <td colspan="2">Data</td>				Compliance		Description		Data		Compliance		Description		Data	
				N/A		Ramp Length (in)		84.0	N/A		Grade Break?		N/A		0.0
Yes		Ramp Width (in)		68.0	N/A		Grade Break Slope (%)		N/A		0.0				
No		Ramp Slope (%)		10.1	N/A		Grade Break XSlope (%)		N/A		0.0				
No		Ramp XSlope (%)		3.3											
N/A		Flare Type LT		N/A	N/A		Flare Type RT		N/A		N/A				
N/A		Flare Slope LT (%)		N/A	N/A		Flare Slope RT (%)		N/A		0.0				
N/A		Flare Traversable LT?		N/A	N/A		Flare Traversable RT?		N/A		N/A				
N/A		Landing Length (in)		0.0	N/A		DWS Provided?		N/A		N/A				
N/A		Landing Width (in)		0.0	N/A		DWS Contrast?		N/A		N/A				
N/A		Landing Slope (%)		0.0	N/A		DWS Length (in)		N/A		N/A				
N/A		Landing X Slope (%)		0.0	N/A		DWS Full Width?		N/A		N/A				
N/A		Landing Curb? (Y/N)		N/A	N/A		DWS Offset LT (in)		N/A		N/A				
N/A		Shared Landing?		N/A	N/A		DWS Offset RT (in)		N/A		N/A				
N/A		Gutter Ponding?		0.0	N/A		Gutter Slope (%)		N/A		N/A				
N/A		Gutter Lip Ht (in)		1.0	N/A		Gutter X Slope (%)		N/A		N/A				
N/A		Painted X Walk1?		No			Road Slope (%)				2.1				
		X Walk 1 Direction		To N			Road X Slope (%)				2.0				
		X Walk 1 Width (in)		N/A			Clear Space?				N/A				
		X Walk 1 Slope (%)		2.1	N/A		Clear Space to XWalk (in)		N/A		N/A				
		X Walk 1 X Slope (%)		2.0	N/A		Storm Grate/Utility Hazard?		N/A		N/A				
N/A		Ramp inside XWalk1?		N/A			Storm Grate/Utility Type								
N/A		Any Obstructions?		N/A							N/A				
		Obstruction Type			Yes		Surface Condition? (G/P)		Good						
				N/A	N/A		Curb Slope (%)		3.6						
Total Cost:				\$	1600.00										

