

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 20759Main Street: COLONY_CROSSING_DRCross Street: COLONY_RDLocation:NEADA ID: C3AF1AECC4E4Ramp Type: Directional1Initial Pass/Fail: FailOverall Compliance: NoSeverity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
COLONY CROSSING DR
Stop Condition-Street 1
None
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Remove & Replace Entire Ramp.						
Surveyor Notes:						
N/A						
PROW/ADA:						
R304.2.2						

Total Cost:	\$	1600.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	81.0	N/A	Grade Break?	N/A			
Yes	Ramp Width (in)	71.0	N/A	Grade Break Slope (%)	0.0			
No	Ramp Slope (%)	8.9	N/A	Grade Break XSlope (%)	0.0			
Yes	Ramp XSlope (%)	3.7						
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A			
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A			
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	No		Road Slope (%)	1.2			
	X Walk 1 Direction	To SE		Road X Slope (%)	5.4			
	X Walk 1 Width (in)	N/A		Clear Space?	N/A			
	X Walk 1 Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A			
	X Walk 1 X Slope (%)	5.4	N/A	Storm Grate/Utility Hazard?	N/A			
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type				
N/A	Any Obstructions?	N/A			N/A			
	Obstruction Type		Yes	Surface Condition? (G/P)	Good			
		N/A	N/A	Curb Slope (%)	9.6			





