## cole

## **Access Compliance Report** Public Rights-of-Way (Curb Ramps)



Intersection ID: 10038034	ersection ID: 10038034 Main Street: SHOPTON_RD_WEST				Cross Street: N/A				Location:	Ν
ADA ID: C3C76B26BCDB	Ramp Ty	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Complian			ce: N	o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
Possible Solutions:					Compliance Description			Data Compliance Description		
A The motor	1 200 MM	Remove & Replace	Entire Ram	p.	N/A	Ramp Length LT (in)	76.0	N/A	Ramp Length RT (in)	48.0
	Service States				Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0
	and the second				Yes	Ramp Slope LT (%)	5.2	Yes	Ramp Slope RT (%)	2.8
					No	Ramp XSlope LT (%)	2.2	Yes	Ramp XSlope RT (%)	1.0
					N/A	Ramp Length (in)	114.0	No	Ramp Slope (%)	9.7
					Yes	Ramp Width (in)	69.0	Yes	Ramp XSlope (%)	0.9
	1 Martin 1	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Shitte and	RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
SHOPTON	RDWEST				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A A A A A A	V mal 17				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
a a a					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
1 ANT		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
· ·	A Station	Not Found, R304.2.	2. R304.5.3		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second second second	AL ANTI	,	_,		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
· · ·	SX 1 12 -				N/A	Shared Landing?	N/A			
Y OF	A HEL				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	None	-			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	SHOPTON RD WEST				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	104.0		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				and the local	int-			N/A	Any Obstruction?	N/A
			1 I		Patrice .				Obstruction Type	
		22 000			al la					N/A
			and an aller					N/A	Storm Grate/Utility Hazard?	N/A
		- Classific				1			Storm Grate/Utility Type	IN/A
	similar 7 letters			State of the state of the	Party and the property	Restance of the second second				N1/A

N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 5.3





