

Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 6363	Main Street: IREDELL_DR	Cross Street: MILHAVEN_LN	Location: NE
ADA ID: C3DC07056F26	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 13.75	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	77.0	N/A
			Yes	Ramp Width (in)	61.0	N/A
			No	Ramp Slope (%)	8.9	N/A
			No	Ramp XSlope (%)	4.0	N/A
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	0.0	N/A
			N/A	Landing Width (in)	0.0	N/A
Surveyor Notes: N/A PROW/ADA: R304.2.2, R304.5.3			N/A	Grade Break?	N/A	N/A
			N/A	Grade Break Slope (%)	0.0	N/A
			N/A	Grade Break XSlope (%)	0.0	N/A
			N/A	Flare Type RT	N/A	N/A
			N/A	Flare Slope RT (%)	0.0	N/A
			N/A	Flare Traversable RT?	N/A	N/A
			N/A	DWS Provided?	N/A	N/A
			N/A	DWS Contrast?	N/A	N/A
			N/A	DWS Length (in)	N/A	N/A
			N/A	DWS Full Width?	N/A	N/A
Total Cost: \$ 1600.00			N/A	DWS Offset LT (in)	N/A	N/A
			N/A	DWS Offset RT (in)	N/A	N/A
			N/A	Gutter Slope (%)	N/A	N/A
			N/A	Gutter X Slope (%)	N/A	N/A
			N/A	Road Slope (%)	0.9	N/A
			N/A	Road X Slope (%)	7.2	N/A
			N/A	Clear Space?	N/A	N/A
			N/A	Clear Space to XWalk (in)	N/A	N/A
			N/A	Storm Grate/Utility Hazard?	N/A	N/A
			N/A	Storm Grate/Utility Type	N/A	N/A
Obstruction Type Yes N/A			N/A	Surface Condition? (G/P)	Good	Good
			N/A	Curb Slope (%)	10.7	N/A
			N/A			
			N/A			
			N/A			
			N/A			
			N/A			
			N/A			
			N/A			
			N/A			

