


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 11659	Main Street: E_16TH_ST	Cross Street: N_DAVIDSON_ST	Location: E
ADA ID: C48690EDA0BB	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 33.75

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
	Possible Solutions:	Compliance	Description	Data	Compliance
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	No	Ramp Length (in)	59.0	No
		No	Ramp Width (in)	43.0	No
		N/A	Flare Type LT	N/A	N/A
		N/A	Flare Slope LT (%)	N/A	N/A
		N/A	Flare Traversable LT?	N/A	N/A
		N/A	Landing Length (in)	N/A	N/A
		N/A	Landing Width (in)	N/A	N/A
		N/A	Landing Slope (%)	N/A	N/A
		N/A	Landing X Slope (%)	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.2.2, R304.5.3</p>		N/A	Flare Type RT	N/A	N/A
		N/A	Flare Slope RT (%)	N/A	N/A
		N/A	Flare Traversable RT?	N/A	N/A
		N/A	DWS Provided?	N/A	N/A
		N/A	DWS Contrast?	N/A	N/A
		N/A	DWS Length (in)	N/A	N/A
		N/A	DWS Full Width?	N/A	N/A
		N/A	DWS Offset (in)	N/A	N/A
		N/A	Gutter Ponding?	N/A	N/A
		N/A	Gutter Lip Ht (in)	N/A	N/A
<p>Total Cost:</p> <p>\$ 3200.00</p>		No	Painted X Walk1?	No	N/A
		N/A	X Walk 1 Direction	To NW	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A
		N/A	X Walk 1 Slope (%)	4.8	N/A
		N/A	X Walk 1 X Slope (%)	0.3	N/A
		N/A	Ramp inside XWalk1?	N/A	N/A
		N/A	Road Slope (%)	2.8	N/A
		N/A	Road X Slope (%)	4.6	N/A
		N/A	Any Obstructions?	N/A	N/A
		N/A	Obstruction Type		N/A
		N/A	Storm Grate/Utility Hazard?	N/A	N/A
		N/A	Storm Grate/Utility Type		N/A
		Yes	Surface Condition? (G/P)	Good	Good

