

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.0

5.4

Intersection ID: 49315 Main Street: ANNA_JORDAN_DR **Cross Street: ROCKLAND DR** Location: Ε **Overall Compliance: No** ADA ID: C4874E73646E Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

48.5 No

48.0 No

Data Compliance Description

Ramp Slope (%)

Ramp XSlope (%)



Possible Solutions:	Comp	liance	Description
Remove & Replace Entire Ramp.	N/A	Ram	c Length (in)
·	Yes	Ram	o Width (in)
	N/A	Flare	Type LT
	N/A	Flare	Slope LT (%)
	N/A	Flare	Traversable L1
	N/A	Land	ing Length (in)
Surveyor Notes:	N/A	Land	ing Width (in)
N/A	N/A	Land	ing Slope (%)
	N/A	Land	ing X Slope (%
	N/A	Land	ing Curb? (Y/N
	N/A	Share	ed Landing?
PROW/ADA:	N/A	Gutte	er Ponding?
Not Found, R304.2.2, R304.5.3	N/A	Gutte	er Lip Ht (in)
	N/A	Paint	ed X Walk1?
		X Wa	lk 1 Direction
	N/A	X Wa	ılk 1 Width (in)
		X Wa	lk 1 Slope (%)
		X Wa	lk 1 X Slope (%
	N/A	Ram	o inside XWalk
		Road	Slope (%)

-1		



The state of the s	The second secon									
	2.0				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	一个种型。数				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	" "一个"大"。	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
TO DES	3 C MATAELY	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
The state of the s	The state of the s				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
California					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2, R304	.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	11/11	, ,			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
						X Walk 1 Direction	To W		X Walk 2 Direction	N/A
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ROCKLAND DR					X Walk 1 Slope (%)	10.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	4.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A
								Yes	Surface Condition? (G/P)	Good
To committee of the same										