

Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 54301	Main Street: GOLF_LINKS_DR	Cross Street: PROVIDENCE_FARM_LN	Location: NW
ADA ID: C4C8576928D1	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 15.25			



Possible Solutions:

**Remove & Replace Entire Ramp.
Grind Gutter Lip.**

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3, R304.5.2, R302.7.2

Total Cost: \$ 1800.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	69.0	No	Grade Break?	No
Yes	Ramp Width (in)	69.0	N/A	Grade Break Slope (%)	0.8
Yes	Ramp Slope (%)	7.3	N/A	Grade Break XSlope (%)	2.2
No	Ramp XSlope (%)	3.5			
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	103.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	69.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.5	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	1.3	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	1.0
N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	30.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.5
No	Gutter Lip Ht (in)	2.0	Yes	Gutter X Slope (%)	2.0
N/A	Painted X Walk1?	No		Road Slope (%)	3.7
	X Walk 1 Direction	To NE		Road X Slope (%)	0.9
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	0.9	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	10.1

Street 1 Name **GOLF LINKS DR**
 Stop Condition-Street 1 **None**
 Street 2 Name **N/A**
 Stop Condition-Street 2 **N/A**

