

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 50042 Main Street: METROPOLITAN_AV Cross Street: S_KINGS_DR Location: NE

ADA ID: C4D9E5DBA9AB Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution



Street 1 Name
Stop Condition-Street 2
Signal
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:					
Remove & Replace Entire Ramp.					
Surveyor Notes:					
N/A					
PROW/ADA:					
Not Found, R304.2.2					

THE BOAR PROPERTY AND A SECOND AS A SECOND

Total Cost:



1850.00

Field Measurements/Component Compliance								
Compl	iance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	8.7			
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.2			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	115.0	N/A	X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			