

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29384 Main Street: KIERNAN_DR Cross Street: PLEASANT_DALE_DR Location: NW
ADA ID: C4FF7BAF1085 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Codes/Mitigation Info/Possible Solution



Street 1 Name
PLEASANT DALE DR
Stop Condition-Street 2
None
Street 2 Name
N/A
Stop Condition-Street 1
N/A

	Possible Solutions:	9
3	Remove & Replace Entire Ramp.	ı
d)
		1
		1
	Surveyor Notes:	N N
S. Contraction	N/A	1
		N
		1
		N
1	PROW/ADA:	1
	Not Found, R304.2.2, R304.5.3	N
Sales .		N
No.		ŀ
		N





Total Cost:



1850.00

Field Measurements/Component Compliance								
Compliance Description		Data	Compl	iance Description	Data			
N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	8.4			
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.6			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	4.5		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			