

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 52612 Main St	Main Street: GRAHAM_RIDGE_DR			LEXANDER_VILLA	Location:	SW		
ADA ID: C5004FF3231B Ramp T	ype: Directional1	Initial Pass/Fail: Pass Overall Compliance: N				nce: No	o Severity Score:	0
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
	Possible Solutions:	Compliance Description				Data Compliance Description		
	Remove & Replace Landing.	N/.	a F	Ramp Length (in)	104.0	N/A	Grade Break?	N/A
		Ye	s F	Ramp Width (in)	66.0	N/A	Grade Break Slope (%)	0.0
		Ye	s F	Ramp Slope (%)	4.6	N/A	Grade Break XSlope (%)	0.0
		Ye	s F	Ramp XSlope (%)	0.2			
MARNOR WULLIER MAN DR &		Ye	s F	Flare Type LT	N/A	Yes	Flare Type RT	N/A
		N//	4 F	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Surveyor Notes:	N//	4 F	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
	N/A	Ye	s L	Landing Length (in)	92.0	Yes	DWS Provided?	Yes
		Ye	s L	Landing Width (in)	68.0	Yes	DWS Contrast?	Yes
		No	L	Landing Slope (%)	4.1	Yes	DWS Length (in)	24.0
		Ye	s L	Landing X Slope (%)	1.1	Yes	DWS Full Width?	Yes
	PROW/ADA:	N//	A L	Landing Curb? (Y/N)	No	Yes	DWS Offset LT (in)	24.0
	R304.2.2-Perp, R304.3.2-Para	N//	A S	Shared Landing?	No	Yes	DWS Offset RT (in)	0.0
		Ye	s (Gutter Ponding?	No	Yes	Gutter Slope (%)	0.2
		Ye	s (Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.7
		N//	A F	Painted X Walk1?	Yes		Road Slope (%)	0.1
Street 1 Name GRAHAM RIDGE DR			>	X Walk 1 Direction	To NE		Road X Slope (%)	1.2
Stop Condition-Street 1 StopSign			>	X Walk 1 Width (in)	102.0		Clear Space?	Yes
Street 2 Name N/A			>	X Walk 1 Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2 N/A			>	X Walk 1 X Slope (%)	1.2	Yes	Storm Grate/Utility Hazard?	No
		Ye	s F	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
		Ye	s A	Any Obstructions?	No			N/A
	Total Cost: \$	500.00	(Obstruction Type		Yes	Surface Condition? (G/P)	Good
					N/A	Yes	Curb Slope (%)	0.5

