

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24849 Main Street: KING_EIDER_DR **Cross Street: WIDGEON_CT** Location: NE Ramp Type: Directional1 **Overall Compliance: No** ADA ID: C51653A25C8E Initial Pass/Fail: Fail **Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution



Street 1 Name **WIDGEON CT** Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions:						
Remove & Replace Entire Ramp.						
Surveyor Notes:						
N/A						
PROW/ADA:						
R304.5.3						

R304.5.3		
Total Cost:	\$ 1600.00	

Field Measurements/Component Compliance								
Compli	ance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	22.0	N/A	Grade Break?	N/A			
Yes	Ramp Width (in)	48.0	N/A	A Grade Break Slope (%)				
Yes	Ramp Slope (%)	6.6	N/A	I/A Grade Break XSlope (%)				
No	Ramp XSlope (%)	5.3						
N/A	Flare Type LT	N/A	N/A	A Flare Type RT				
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A			
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A			
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	No		Road Slope (%)	3.3			
	X Walk 1 Direction	To S		Road X Slope (%)	3.6			
	X Walk 1 Width (in)	N/A		Clear Space?	N/A			
	X Walk 1 Slope (%)	3.3	N/A	Clear Space to XWalk (in)	N/A			
	X Walk 1 X Slope (%)	3.6	N/A	Storm Grate/Utility Hazard?	N/A			
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type				
N/A	Any Obstructions?	N/A			N/A			
	Obstruction Type		Yes	Surface Condition? (G/P)	Good			
		N/A	N/A	Curb Slope (%)	34.4			





