

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 7725	Main Street: HIDDEN_VALLEY_RD	Cross Street: W_SUGAR_CREEK_RD	Location: SW
ADA ID: C5AE0F529410	Ramp Type: Para	Initial Pass/Fail: Pass	Overall Compliance: No
Severity Score: 0.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

CURB GAP 1.0, RT RP < 5%

PROW/ADA:

Not Found, R304.5.3, R304.2.2-Perp, R304.3.2-Para

Total Cost: \$ 1600.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	71.0	N/A	Ramp Length RT (in)	72.0
Yes	Ramp Width LT (in)	48.0	Yes	Ramp Width RT (in)	48.0
Yes	Ramp Slope LT (%)	6.3	Yes	Ramp Slope RT (%)	2.7
Yes	Ramp XSlope LT (%)	1.9	No	Ramp XSlope RT (%)	3.3
Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	48.5	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	4.5	Yes	DWS Length (in)	25.0
No	Landing X Slope (%)	2.7	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.5
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.6
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	119.0	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A
Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			Replace	Curb Slope (%)	16.4

