## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29419 Main Street: BRADSTREET_COMMONS_WYCross Street: DONET_TERRACE_DR Locat										NW	
ADA ID: C5E409688E72						nitial Pass/Fail: Fail Overall Compliance: No				25	
· · · ·				IIIItiai	r ass/1 e			25			
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description				
and a presidence		Remove & Replace Entire	Ram	ıp.	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	7.9	
					Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	10.0	
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Maria Maria					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
TELES .		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
e e e e e e e e e e e e e e e e e e e		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
BRADSTREET		2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		-			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
Alles and the	the second	-			N/A	Shared Landing?	N/A				
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
A Distance of States	the state on	Not Found, R304.5.3			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
A on the last						X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
	Alter Alter Y				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	DONET TERRACE DR					X Walk 1 Slope (%)	6.7		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	6.1		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	

**Yes** Surface Condition? (G/P)

Good

