

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 8221	Main Street: HUNTERS_GLEN_DR	Cross Street: RUNNING_DEER_RD	Location:	N/A
ADA ID: C691AEC915CA	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 8.75
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance		

	Possible Solutions:		Compliance		Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	49.0	Yes	Ramp Slope (%)	5.2	
			No	Ramp Width (in)	43.0	Yes	Ramp XSlope (%)	0.5	
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
			N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
			X Walk 1 Direction	To W		X Walk 2 Direction	N/A		
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
			X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	N/A		
			X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	N/A		
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
			Road Slope (%)	0.6	N/A	Clear Space?	N/A		
			Road X Slope (%)	1.5	N/A	Clear Space to XWalk (in)	N/A		
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
			Obstruction Type			Storm Grate/Utility Type			
					N/A		N/A		
					Yes	Surface Condition? (G/P)	Good		

Street 1 Name	RUNNING DEER RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Total Cost:	\$	1850.00
-------------	----	---------

