


Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29320 Main Street: N_TRYON_ST Cross Street: UNIVERSITY_EXECUTIVE_PARK_DR Location: NW ADA ID: C6B904C89DEB Ramp Type: Directional1 Initial Pass/Fail: Pass **Overall Compliance: Yes Severity Score:**

> **Codes/Mitigation Info/Possible Solution** Field Measurements/Component Compliance



UNIVERSITY EXECUTIVE PARK DR Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A

itions:	Comp	oliance Description	Data	Compli	ance Description	Data
	N/A	Ramp Length (in)	96.0	N/A	Grade Break?	N/A
	Yes	Ramp Width (in)	91.0	N/A	Grade Break Slope (%)	0.0
	Yes	Ramp Slope (%)	3.2	N/A	Grade Break XSlope (%)	0.0
	Yes	Ramp XSlope (%)	0.3			
	Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
es:	N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
	Yes	Landing Length (in)	61.0	Yes	DWS Provided?	Yes
	Yes	Landing Width (in)	96.0	Yes	DWS Contrast?	Yes
	Yes	Landing Slope (%)	0.3	Yes	DWS Length (in)	24.0
	Yes	Landing X Slope (%)	1.2	Yes	DWS Full Width?	Yes
	N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset LT (in)	0.0
	N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	0.0
	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.1
	Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.1
	N/A	Painted X Walk1?	Yes		Road Slope (%)	2.1
		X Walk 1 Direction	To S		Road X Slope (%)	2.5
		X Walk 1 Width (in)	100.0		Clear Space?	Yes
		X Walk 1 Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
		X Walk 1 X Slope (%)	2.5	Yes	Storm Grate/Utility Hazard?	No
	Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
	Yes	Any Obstructions?	No			N/A
\$ 0.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Yes	Curb Slope (%)	6.6





N/A

N/A

N/A

Total Cost:

