cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · · · · · · · · · · · · · · · · ·									
Intersection ID: 28624	Main St	Main Street: PEDLAR_MILLS_RD			STUARTS_DRAFT_C	Location:	NW		
ADA ID: C6D24E836FC2	2 Ramp T	Ramp Type: PerpDiag			ail: Pass Overall	o Severity Score:	10		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp \	Nith	N/A	Ramp Length (in)	50.0	Yes	Ramp Slope (%)	5.5
		Two New Directional Ramps or		Yes	Ramp Width (in)	70.0	Yes	Ramp XSlope (%)	0.6
		Equivalent.		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	4.0	N/A	Flare Slope RT (%)	10.9
		2		N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
				No	Landing Length (in)	44.0	No	DWS Provided?	No
1		Surveyor Notes:		Yes	Landing Width (in)	51.0	N/A	DWS Contrast?	No
E Contraction		N/A		Yes	Landing Slope (%)	1.5	N/A	DWS Length (in)	N/A
to a the last				Yes	Landing X Slope (%)	1.9	N/A	DWS Full Width?	No
NELS	101.5			N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
Bais				N/A	Shared Landing?	No			
GUOLISS.		PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.2
		R304.2.1, R305		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.6
in the second second				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
17 1 1 1 1				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE	
Simple 1				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	STUARTS DRAFT CT	-			X Walk 1 Slope (%)	3.6		X Walk 2 Slope (%)	4.0
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	4.6
Street 2 Name	PEDLAR MILLS RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	2.9	N/A	Clear Space?	Yes
					Road X Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

