

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

67.0

59.0

1.7

0.3

8.4

1.2

N/A

Intersection ID: 44424 Main Street: S TRYON ST Cross Street: SAVANNAH POINT DR Location: SE **Overall Compliance: No Severity Score:** 12.5 ADA ID: C6E4F8FA3B70 Ramp Type: Combination1 Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Nο

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

Flare Traversable RT?

Data

48.0

59.0

6.3

2.0

49.0

50.0

N/A

No

To W

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name StopSign Stop Condition-Street 1 SAVANNAH POINT DR N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes Yes Yes N/A Yes Surveyor Notes: N/A MEDIAN ACROSS S TRYON ST, RT N/A **RP < 5%** N/A N/A N/A PROW/ADA: N/A Not Found, R304.2.2 N/A N/A N/A N/A N/A N/A

Total Cost:





