

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

4.7

2.3

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 12820 Main Street: DEARMON DR Cross Street: DUNHILL DR Location: N **Overall Compliance: No Severity Score:** 10 **ADA ID: C6FB78AB5475** Ramp Type: BlendTrans1 Initial Pass/Fail: Fail

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Flare Traversable LT?

Flare Type LT

N/A

No

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Flare Type RT

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Flare Traversable RT?

BlendTrans Slope (%)

BlendTrans XSlope (%)

Data

42.0

47.5

N/A



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2 Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

N/A

PROW/ADA:





Not Found, R304.5.1, R304.5.3 N/A Gutter Lip Ht (in) 1.0 N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To SW X Walk 2 Direction N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A **DUNHILL DR** X Walk 1 Slope (%) 8.5 X Walk 2 Slope (%) N/A StopSign X Walk 1 X Slope (%) 0.7 X Walk 2 X Slope (%) N/A N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? N/A N/A Road Slope (%) 0.7 Clear Space? N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A 8.5 N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A Total Cost: **Obstruction Type** 3200.00 Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good No Curb Slope (%) 12.5