

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12653 Main Street: N_MYERS_ST Cross Street: E_8TH_ST Location: W

ADA ID: C700FED1F689 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

N MYERS ST StopSign E 8TH ST None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

r leid Measurements/Component Comphance						
Compliance Description		Data	Compliance Description		Data	
N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	9.8	
Yes	Ramp Width (in)	91.0	No	Ramp XSlope (%)	4.9	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	X Walk 1 Direction	To SE		X Walk 2 Direction	To NE	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	2.0	
	X Walk 1 X Slope (%)	7.3		X Walk 2 X Slope (%)	4.1	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	2.4	N/A	Clear Space?	N/A	
	Road X Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
			1			

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Good







Obstruction Type